



PRELIMINARY ANALYSIS OF DATA FROM THE AFTERSHOCK DEPLOYMENT IN VAN AND ERCİŞ , TURKEY

AFTERSHOCKS WITH M≥4.0

Department of Earthquake Engineering Kandilli Observatory and Earthquake Research Institute Bogazici University Istanbul, Turkey

December 2011





SUMMARY

Following the destructive M=7.2 Van Earthquake of 23 October 2011 in Eastern Turkey, we have deployed eight strong motion monitoring equipment to the region to record aftershocks.

Four of the stations were installed in the city of Van, and the remaining four in the city of Erciş, which suffered the most damage and loss of life. The stations in each city are arranged such that one of the stations is located on a stiff soil or a rock site to be used as the reference station, and the remaining three in the flat urban area forming a triangle.

The eight-station network has recorded a large number of aftershocks, including the destructive one with M=5.6 on 9 November 2011 epicentered near the town of Edremit south of Van. Figure 1 shows the deployment regions. The locations of the eight stations in Van and Erciş can be seen Figures 2 and 3 respectively. Descriptive information on the stations is summarized in Table 1.

This document reports on the records from earthquakes with M≥4.0 that were obtained until 3 November 2011 and on the events with M≥4.9 in the period of 03-21 November 2011. All together ten events are considered in this report. The events before 9 November are essentially the aftershocks of the 23 October 2011, Mw7.2 earthquake. All of the reported earthquakes were recorded by the stations in Erciş, whereas in Van only three earthquakes were recorded by two of the four stations. The records can be downloaded through links in Table 2 and Table 3. Table 2 covers events with M≥4.0 in the period of 1-3 November 2011. Table 3 are for the M≥4.9 events between 3 and 21 November 2011. The epicentral properties of all events can be found in Table 4.

Six earthquakes are selected for analysis among the presented ten. The first one is the M4.7 earthquake of 02.11.2011. The second earthquake is the Şahgeldi event, which took place on the same date with the first one, was however recorded by five stations. Processed records from the Akçift event (M4.7) can be seen in pages 11-20. The records of the Şahgeldi event (M4.4) are presented in pages 21-34. The records from the M4.9 Çolpan event are given in pages 35-44, M5.5 Vangölü in pages 45-62, Mollakasım in 63-80 and finally Bodurağaç records are given in pages 81-90.

At link

http://www.koeri.boun.edu.tr/Haberler/23%20October%202011,%20Mw=7.2%20Van,%20Turk ey%20Eq. 6 205.depmuh, information on the 23 October 2011 earthquake can be found.





For the background information on the 9 November 2011, M5.6 earthquake please see the link <u>http://www.koeri.boun.edu.tr/Haberler/THE%20NOVEMBER%2009,%202011%20EDREMIT-VAN,%20TURKEY%20EARTHQUAKE_6_207.depmuh.</u>

Analysis of records from the 9 November 2011, M5.6 earthquake is covered in a seperate report at link <u>http://www.koeri.boun.edu.tr/depremmuh/deprem-raporlari/Van_Eq_aftershocks1.pdf</u>.







Figure 1. Locations of aftershock monitoring cities, Van and Erciş








Figure 2. Locations of aftershock monitoring stations in Van








Figure 3. Locations of aftershock monitoring stations in Erciş





Table 1. Station information for the Van and Erciş deployments.

VAN					
STATION CODE	STATION COORDINATES	STATION LOCATION			
VNS (rock site)	38.33455N 43.19533E	Şemsibey İlkokulu			
VNKIO (soil site)	38.33455N 43.19533E	Koç İlköğretim Okulu			
VNTGM (soil site)	38.33455N 43.19533E	TEDAŞ Genel Müdürlüğü (Havaalanı kavsağı)			
VNKEA (soil site)	38.33455N 43.19533E	TEDAŞ Köy Elektrik Arıza (Valilik yanı, Santral Sok.)			

ERCİŞ					
STATION CODE	STATION COORDINATES	STATION LOCATION			
ERSFB (stiff soil site)	38.59996N 43.27304E	Erciş Şeker Fabrikası			
ETR (soil site)	39.00880N 43.21097E	TEDAŞ Trafo Binası (Çınarlı Caddesi sonu)			
ERKRY(soil site)	39.02264N 43.21426E	Erciş Karayolları 115. Şube Müdürlüğü			
ERISF(soil site)	39.01398N 43.20798E	Yüzüncü Yıl Üniversitesi Erciş İşletme Fakültesi			





Table 2. Aftershock records (01.11.2011-03.11.2011, M≥4.0)

STA	TIONS AND AFTERSHOCKS	Sağlamtaş M=4.3 01/11/2011 23:10:44	Çakırbey M=4.8, 02/11/2011 06:34:20	Akçift M=4.7 02/11/2011 15:24:02	Şahgeldi M=4.4 02/11/2011 22:48:21	Çolpan M=4.1 02/11/2011 23:44:15	Unseli- Muradiye M=4.0 03/11/2011 03:05:46
	VNS						
	38.33445N – 43.19533E						
	Şemsibey İlkokulu						
	VNKIO						
7	38.30957N – 43.20473E				<u>X</u>		
VAN	Koç İlköğretimokulu						
\mathbf{N}	VNTGM				V		
	38.28571N – 43.21571E TEDAS Concl Müdürlüğü				X		
	TEDAŞ Genel Müdürlüğü VNKEA						
	VINKEA 38.30070N – 43.23898E						
	TEDAŞ Köy Elektrik Arıza						
	ERSFB						
	28.59996N – 43.27304E	X	<u>X</u>	<u>X</u>		X	X
	Erciş Şeker Fabrikası	$\underline{\Lambda}$	Δ	$\underline{\Lambda}$		$\underline{\Lambda}$	<u>A</u>
	ETR						
	39.00880N – 43.21097E			<u>X</u>	<u>X</u>	X	<u>X</u>
ĊİŞ	TEDAŞ Trafo						
ERCİŞ	ERKRY						
	39.02264N – 43.21426E	<u>X</u>	X	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>
	Karayolları 115. Şube Müd.	_	_	—	_	_	_
	ERISF						
	39.01398N - 43.20798E	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>
	100. Yıl Üni. İşletme Fak.						





STA	TIONS AND AFTERSHOCKS	Çolpan M=4.9 06/11/2011 02:43:12	Van Gölü M=5.5 08/11/2011 22:05:15	Mollakasım M=5.2 14/11/2011 22:08:15	Bodurağaç M=4.9 18/11/2011 17:39:40
VAN	VNS 38.33445N – 43.19533E		X	X	
	Şemsibey İlkokulu VNKIO				
	38.30957N – 43.20473E Koç İlköğretimokulu	X			
	VNTGM 38.28571N – 43.21571E				
	TEDAŞ Genel Müdürlüğü VNKEA				Y
	38.30070N – 43.23898E TEDAŞ Köy Elektrik Arıza		X	X	X
ERCİŞ	ERSFB 38.59996N – 43.27304E Erciş Şeker Fabrikası	<u>X</u>	X	X	X
	ETR 39.00880N – 43.21097E TEDAŞ Trafo	X	X	X	X
	ERKRY 39.02264N – 43.21426E Karayolları 115. Şube Müd.	<u>X</u>	X	<u>X</u>	X
	ERISF 39.01398N – 43.20798E 100. Yıl Üni. İşletme Fak.	X	X	X	X

Table 3. Aftershock records (03.11.2011-21.11.2011, M≥4.9)





Date	Latitude	Longitude	Depth	Magnitude	
01.11.2011 23:10:44	38.881N	43.581E	5.0	4.3	Sağlamtaş (Van)
02.11.2011 06:34:20	38.873N	43.569E	5.0	4.8	Çakırbey (Van)
02.11.2011 15:24:02	38.856N	43.578E	5.0	4.7	Akçift (Van)
02.11.2011 22:48:21	38.761N	43.321E	5.0	4.4	Şahgeldi (Van)
02.11.2011 23:44:15	38.939N	43.553E	5.0	4.1	Çolpan (Van)
03.11.2011 03:05:46	38.958N	43.588E	5.0	4.0	Unseli- Muradiye (Van)
06.11.2011 02:43:12	38.924N	43.565E	5.0	4.9	Çolpan (Van)
08.11.2011 22:05:51	38.724N	43.087E	4.3	5.5	Van Gölü (Van)
14.11.2011 22:08:15	38.678N	43.182E	3.1	5.2	Mollakasım (Van)
18.11.2011 17:39:40	38.837N	43.870E	5.0	4.9	Bodurağaç (Van)






Akçift/Van Aftershock M=4.7 02/11/2011 15:24:02

ERCİŞ RECORDS




































































Şahgeldi/Van Aftershock M=4.4 02/11/2011 22:48:21

VAN RECORDS















































Şahgeldi/Van Aftershock M=4.4 02/11/2011 22:48:21

ERCİŞ RECORDS








29
























-0.04 L

Boğaziçi University Kandilli Observatory and Earthquake Research Institute Department of Earthquake Engineering



M=4.4 SAHGELDI ON 02/11/2011 AT 22:48:21



TIME (s)

15


20

25

10












Çolpan/Van Aftershock M=4.9 06/11/2011 02:43:12

ERCİŞ RECORDS




































































Van Gölü/Van Aftershock M=5.5 08/11/2011 22:05:51

ERCİŞ RECORDS































-0.5

Boğaziçi University Kandilli Observatory and Earthquake Research Institute **Department of Earthquake Engineering**





25 TIME (s)

15

20


45

50

35




































Van Gölü/Van Aftershock M=5.5 08/11/2011 22:05:51

VAN RECORDS

























































Mollakasım/Van Aftershock M=5.2 14/11/2011 22:08:15

ERCİŞ RECORDS







































































Mollakasım/Van Aftershock M=5.2 14/11/2011 22:08:15

VAN RECORDS

























































Bodurağaç/Van Aftershock M=4.9 18/11/2011 17:39:40

ERCİŞ RECORDS



























Boğaziçi University Kandilli Observatory and Earthquake Research Institute **Department of Earthquake Engineering**








Boğaziçi University Kandilli Observatory and Earthquake Research Institute Department of Earthquake Engineering









Boğaziçi University Kandilli Observatory and Earthquake Research Institute Department of Earthquake Engineering

























Contributed by: E. Çaktı, O. Çırağ, N. Kafadar, A. Korkmaz, E. Şafak, E. Uçkan (alphabetical)